



Photo 4.22 Reconstruction of the main sewage line in Hernandez Avenue of Dagupan City. High level of ground water table.



Photo 4.23 View on the Hernandez Avenue and concrete pipes taken out from the sewage line in Dagupan City.



Photo 4.24 Elevated steel water tank near Dagupan City. No damage reported, could be attributed to specific frequency content of earthquake ground motions.