

Fig. 31 Detail of shear damage in coupling beams.




Fig. 32 Shear cracks in concrete walls near window openings.



Fig. 33 Shear cracking in columns and wall piers at the second floor in St. John's Hospital.