



Fig. 51 CSUN parking building. Note RC column ductility




Fig. 52 CSUN parking structure. Note brackets for supporting precast girders and minimal continuity reinforcement.