


Photos 3.19 Typical landslide and rockfall of small volume, producing damage to agricultural land.



Photos 3.20 Intensive medium scale rockfall on the Marcos Highway approaching Baguio City.



Photos 3.21 Large scale rockfalls on Kennon Road (after 3).