



Fig. 28 Column flexural hinging.



Fig. 29 Impressive buckling of steel bars and concrete crushing along the height.



Fig. 30 General view of the Santa Monica Hospital.